



Hieroby certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to:

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

On 4/15/03

FOWNSEND and TOWNSEND and CREW LLP

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re application of:

Examiner:

Alonzo Chambliss

Maria C. Y. Quinones, et al.

Art Unit:

2814

Application No.: 09/487,969

37 C.F.R. § 1. 131

DECLARATION UNDER

Filed: January 18, 2000

IMPROVED METHOD OF

MAKING A CHIP DEVICE

Sir:

We, Maria Clemens Y. Quinones, Gilmore S. Baje, Maria Cristina B. Estacio, Marvin R. Gestole, Oliver M. Ledon, and Santos Mepieza, each declare as follows:

- 1. I am a co-inventor of at least one claim in the referenced patent application.
- 2. I have reviewed the Office Action mailed on December 31, 2002, and the obviousness rejections of claims 7-33 based on U.S. Patent No. 6,307,755 to Williams et al.
- 3. The inventions of at least pending independent claims 7, 15, and 23 were conceived of before May 27, 1999, the filing date of Williams et al. Evidence of conception is shown by the attached documents in Exhibit A. Some of the pages in Exhibit A include initials and dates of January 5 and 6, 1999.

Maria C. Estacio, et al. Application No.: 09/548,946

Page 2


- 4. Reduction to practice of embodiments of the inventions before May 27, 1999, is evidenced by the documents in Exhibits B and C, which include e-mail communications between one or more co-inventors and others. A die package that was produced according to an embodiment of the invention was referred to internally at Fairchild Semiconductor as "SO-8" wireless. As evidence of reduction to practice, one e-mail communication in Exhibit B states "Wireless samples (SO-8) were sent from Steve Sapp with objective of identifying source of Rdson lower than expected." One e-mail in Exhibit C states "Add top & bottom alignment press-fit studs & holes ... Status: Changes incorporated in Rev. P bottom frame and Rev. N topframe design." The documents in Exhibits B and C were originally created before May 27, 1999 and show that an embodiment of the invention was reduced to practice before May 27, 1999.
- 5. Exhibit D contains correspondence regarding the preparation of a patent application for embodiments of the invention. The correspondence includes: a letter dated June 4, 1999 from Fairchild Semiconductor to Townsend, Townsend & Crew (TTC) requesting the preparation of a patent application; a letter dated June 7, 1999 from TTC acknowledging receipt of the June 4, 1999 letter; a file note dated September 20, 1999 with some invention details; a letter dated November 19, 1999 from TTC to Ms. Quinones with a draft patent application; and an e-mail dated December 5, 1999 with comments on the prior draft patent application.
- 6. As shown by Exhibits A-C, I believe that an embodiment of the invention was conceived of and reduced to practice before May 27, 1999. As shown by Exhibits A-D, embodiments of the invention were also conceived of before May 27, 1999 and were diligently pursued until the filing of the present application.

Page 3

- The acts relied on in this Declaration (and described in the Exhibits) took
 place in a WTO country.
- 8. I hereby declare that all statements made of my own knowledge are true and that all statements made on information and belief are believed to be true. I understand that willful false statements and the like are punishable by fine or imprisonment, or both (18 U.S.C. §1001) and may jeopardize the validity of the application or any patent issuing thereon.

Jacquinnes		
Maria Clemens Y. Quiñones	Date	
Gilmore S. Baje	Date	Production (by any state of the production of th
(II) 4-	Date	
Maria Cristina B. Estacio	Date	
pote		
Maryin R. Gestole	Date	
Oliver M. Ledon	Date	
Santos Mepieza	Date	

60029226 v1



FSC Confidential



High-Performance SOIC-8 DIMOS Package Construction

ACTAMAIS



Part 6: SOIC-8 Molded Outline

- Length = 0.193" typ
- Width = 0.154" typ
- Thickness = 0.057" typ

Part 5: Gate & Source Terminal Contacts

Part 4: Solder Bumps

- Bump Alloy: Pb/Sn or Pb/Sn/Ag or Sn/Sb
- Bump diameter ~ 0.008"
 - Bump Height ~ 0.006"
- · UBM: TiW/Cu/Au or equivalent

Part 3: FSC DMOS Trench Die with Source & Gate Array

Part 2 : Die Attach Material

- Ag-filled Adhesives (Epoxy, polyimide)
 Soft Solder

Part 1: Die Attach Pad

- · Material: Cu alloy
- · DAP plating options: None, Ag, Ni
- DAP support:
- •X-axis: tie bars
- · Y-axis: Drain terminals










High-Performance SOIC-8 DMOS Leadframe Design



FSC Confidential



BOTTOM LEADERAME

Leadframe Part	Function
DAP	Die Attach Pad; Drain connection;
Tie Bar	DAP support; Package support @ lead stage forming
Dambar	Mold flash barrier
Drain Leads	Drain terminals
Rail Upset	Levels drain leads with gate & source leads
x/Alignn	Transport handling feature; Alignment for top & bottom leadframes
Alle 5 142 93 Hagrins Jan's	
Ching 5 la da	




TOP LEADFRAME

Leadframe Part	Function
Source Pad	Connect 3 terminals to source metallizations of die
Gate Pad	Connect 1 terminal to gate metallization of die
Contact Protrusions	Provide good contact between solder bumps of die
Dambar	Mold flash barrier; Leads coplanarity support
Lead Upset	Provides space for solder bumped die
Index/Alignment Hole Rail	Transport handling feature; Alignment for top & bottom leadframes Backbone or main mechanical support of leadframe
STATE TO STATE OF THE STATE OF	




Top & Bottom Leadframe Assembly




FSC Confidential

High-Performance SOIC-8 DMOS Leadframe Easy-Align Feature



TOP & BOTTOM LEADFRAME ASSEMBLY

Bottom Frame Aligners are press-fitted unto top frame alignment holes keeping both leadframes steadily stacked. Press fitting can be integrated right after top frame attach



FSC Confidential

how chen's

HIGH PERFORMANCE SOIC-8 DMOS PROCESS FLOW FRONT END ASSEMBLY OPTIONS (Summary)

	OPTION	OPTION	OPTION	OPTION	OPTION	OPTION	OPTION	OPTION
		7	C	+	n	0	_	0
Step 1	Epoxy Die	Soft Solder Die	Top Frame	Top Frame	Epoxy Die	Top Frame	Epoxy Die	Soft Solder Die
4	Attach	Attach	Fluxing	Fluxing	Attach	Fluxing	Attach	Attach
Step 2	Epoxy Cure	Top Frame	Flip Chip	Flip Chip	Epoxy Cure	Flip Chip	Epoxy Cure	Solder Bump
•		Fluxing	Attach	Attach		Attach		Fluxing
Step 3	Top Frame	Top Frame	Solder Bump	Solder Bump	Top Frame	Bottom Frame	Solder Bump	Top Frame
4	Fluxing	Attach	Reflow	Reflow	Screen Fluxing	Solder Paste	Fluxing	Attach
						Dispense		
Step 4	Top Frame	Solder Bump	Bottom Frame	Bottom Frame	Bottom Frame	Top & Bottom	Top Frame	Rail Spot
•	Attach	Reflow	Epoxy	Solder Paste	Loading	Frame	Attach	Welding
			Dispense	Dispense		Sandwich		
		. :				Assembly		
Step 5	Solder Bump		Top & Bottom	Top & Bottom	Top Frame	Rail Spot	Rail Spot	Solder Bump
-	Reflow		Frame	Frame	Loading	Welding	Welding	Reflow
			Sandwich	Sandwich				
			Assembly	Assembly				
Step 6			Epoxy Cure		Rail Spot		Solder Reflow	
4					Welding			
Step 7					Solder Bump			
•					Reflow			

free cla, 'as

(Hothers (San 99




HI-PERFORMANCE SOIC-8 DMOS

PROCESS FLOW


FRONT END ASSEMBLY, OPTION 1

FSC Confidential





EPOXY CURE




Options: coventional box oven curing, heater block snap curing, or equivalent

FSC Confidential

3




TOP FRAME FLUXING




Top frame fluxing done with gate & source contact pads facing up.

FSC Confidential



Top frame is flipped and mounted to bottom frame assembly.

FSC Confidential



solder bumps and permanently attach die to the topframe.

FSC Confidential



HI-PERFORMANCE SOIC-8 DMOS

PROCESS FLOW


END OF LINE ASSEMBLY, OPTION 1

FSC Confidential

1

FAIRCHILD

MOLDING




SOIC-8 wireless assembly is molded with die facing up.

FSC Confidential



DEBAR & DEJUNK




Dambar & mold flashes are mechanically removed.

FSC Confidential

3





MEDIA DEFLASH



Remaining resin bleeds on leads are removed using pressurized media deflash grits.

FSC Confidential







TRIM & FORM













3-stage forming

NOTE: Sample marking only; context with no definite meaning.

FSC Confidential




HI-PERFORMANCE SOIC-8 DMOS

PROCESS FLOW


FRONT END ASSEMBLY, OPTION 2

FSC Confidential





TOP FRAME FLUXING




Top frame fluxing done with gate & source contact pads facing up.

FSC Confidential

:


FAIRCHILD

TOP FRAME ATTACH



Top frame is flipped and mounted to bottom frame assembly.

FSC Confidential



solder bumps and permanently attach die to the topframe.

FSC Confidential



HI-PERFORMANCE SOIC-8 DMOS

PROCESS FLOW

FRONT END ASSEMBLY, OPTION 3

FSC Confidential


TOP FRAME FLUXING

Top frame fluxing done with gate & source contact pads facing up.

FSC Confidential



FLIP CHIP ATTACH




Die is flipped from from its pick-up position & attached solder bumps facing down to the top frame. Die placement precision requirement is +/- 2 mils.

FSC Confidential

3




SOLDER BUM PREFLOW



Flipped die & topframe are heated to reflow the solder bumps and permanently attach die to the topframe.

FSC Confidential




Conductive epoxy is dispensed on die attach pad.

FSC Confidential

5

TOP & BOTTOM FRAME SANDWICH ASSEMBLY




Flip chip attached top frame is flipped over bottom frame to complete SOIC-8 wireless assembly. Precise alignment is required.

FSC Confidential



EPOXY CURE



Options: coventional box oven curing, heater block snap curing, or equivalent

FSC Confidential



HI-PERFORMANCE SOIC-8 DMOS

PROCESS FLOW

FRONT END ASSEMBLY, OPTION 4

FSC Confidential


TOP FRAME FLUXING

Top frame fluxing done with gate & source contact pads facing up.

FSC Confidential



FLIP CHIP ATTACH




Die is flipped from from its pick-up position & attached solder bumps facing down to the top frame. Die placement precision requirement is +/- 2 mils.

FSC Confidential

3




SOLDER BUMP REFLOW



Flipped die & topframe are heated to reflow the solder bumps and permanently attach die to the topframe.

FSC Confidential

BOTTOM FRAME SOLDER PASTE DISPENSE




Low melting solder paste (relative to die solder bump) is dispensed on die attach pad.

FSC Confidential

5

FAIRCHILD

TOP & BOTTOM FRAME SANDWICH ASSEMBLY



Flip chip attached top frame is flipped over bottom frame to complete SOIC-8 wireless assembly. Precise alignment is required. Whole assembly is done on a heated block.

FSC Confidential




HI-PERFORMANCE SOIC-8 DMOS

PROCESS FLOW

FRONT END ASSEMBLY, OPTION 5


FSC Confidential

ı





EPOXY CURE




Options: coventional box oven curing, heater block snap curing, or equivalent

FSC Confidential

3


FAIRCHILD


TOP FRAME SCREEN FLUXING





Top frame fluxing done with gate & source contact pads facing up.

FSC Confidential












HI-PERFORMANCE SOIC-8 DMOS

PROCESS FLOW

FRONT END ASSEMBLY, OPTION 6

FSC Confidential

1




Top frame fluxing done with gate & source contact pads facing up.

FSC Confidential



FLIP CHIP ATTACH




Die is flipped from from its pick-up position & attached solder bumps facing down to the top frame. Die placement precision requirement is +/- 2 mils.

FSC Confidential

3

BOTTOM FRAME SOLDER PASTE DISPENSE




Low melting solder paste is dispensed on die attach pad.

FSC Confidential



TOP & BOTTOM FRAME SANDWICH ASSEMBLY




Flip chip attached top frame is flipped over bottom frame to complete SOIC-8 wireless assembly. Precise alignment is required. Whole assembly is done on a heated block.

FSC Confidential



RAIL SPOT WELDING



Top & bottom leadframe rails are spot welded together.

FSC Confidential




HI-PERFORMANCE SOIC-8 DMOS

PROCESS FLOW

FRONT END ASSEMBLY, OPTION 7


FSC Confidential



FSC Confidential




EPOXY CURE



Options: coventional box oven curing, heater block snap curing, or equivalent


FSC Confidential

3





TOP FRAME ATTACH




Top frame is mounted to bottom frame assembly.

FSC Confidential

5




RAIL SPOT WELDING



Top & bottom leadframe rails are spot welded together.

FSC Confidential

6






HI-PERFORMANCE SOIC-8 DMOS


PROCESS FLOW


FRONT END ASSEMBLY, OPTION 8


FSC Confidential

1










FSC Confidential

5

6



FSC Confidential



Subject:

>SO-8 Wireless Int rnal Pkg Characterizati ns in Salt Lake

R sp nse to:

EVALUATIONS & LEARNINGS

Categ ry:

Wireless SO-8 Pkg Dev't (Single Strand Approach)

Report 2/5 - Wireless SO-8

----- Forwarded by Steve Pritchett/SaltLake/Fairchild on 04/21/99 06:32 PM -



Steve Pritchett 04/21/99 03:29 PM

To:

Rajeev Joshi/SantaClara/Fairchild@Fairchild, Ma Cristina B Estacio/Cebu/Fairchild@Fairchild, Consuelo N Tangpuz/Cebu/Fairchild@Fairchild, Honorio T Granada Jr/Cebu/Fairchild@Fairchild, Lester O

Uy/Cebu/Fairchild@Fairchild

CC:

Steven Sapp/SantaClara/Fairchild@Fairchild, Bruce Marchant/SaltLake/Fairchild@Fairchild, John R Diroll/SaltLake/Fairchild@Fairchild, R Evan Bendall/SaltLake/Fairchild@Fairchild, Henry W Hurst/SaltLake/Fairchild@Fairchild. Annette Pieper/SaltLake/Fairchild@Fairchild. Gordon

Madson/SaltLake/Fairchild@Fairchild

Subject: Report 2/5 - Wireless SO-8

I have broken this up into 4 emails/reports due to many photos.

- 1. Flipchip samples, some with gate to source shorts, some with black "corrosion" stain. (sent 4-19)
- 2. Wireless samples from Steve Sapp, SO-8 good/bad ?, identify cause of high Rdson.
- 3. SO-8 wireless samples prior to molding, sent per SL request to help understand leadframe layout.
- 4. Bare die samples with bumps, sent per SL request.
- 5. Samples of SOT-223 wireless parts sent to SV, construction analysis. (still in que)

Wireless samples (SO-8) were sent from Steve Sapp with objective of identifying source of Rdson lower than expected. Previous email sent 3-24-99 showing poor UBM to Al pad contact area, leadframe not contacting all bumps and D/A voids (w/ epoxy attach, not standard).

SUMMARY - Same as above just more photos of leadframe alignment and spacing affects. Wicking of solder into molding compound channel could be problem for controlling bump size. Note: JPG files for these photos are available upon request.

As received, some of the parts were labeled good, some bad. We assume this related to Rdson measurement.

The following photos are observations. Cebu will need to access if these are problems, not representative

of current process, etc.



Ext 4 (page 2/7)

This is part # 206, no contact, bump to leadframe at left side. (wire-206a.jpg)



This is part # 206, more bumps contacting than above photo on different bump row. Indicates angled front to back as well as angle side to side shown above. (wire-206b.jpg)



This is part # 245 showing gate pad. Gate leadframe appears to be at different angle than source leadframe. (wire-245a.jpg)



This is part # 245, good horizontal alignment, but assume "squished" bumps? What is desired/acceptable profile? (wire-245b.jpg)



This is part #260. It appears the surface condition of the bump contact leadframe will allow the solder to wick into molding compound channel. Could make bump size and volume difficult to control. The "squished" bumps may allow the bump metal to extend over non-common die metal. For example, a squished gate bump may result in overlap over source metal. Steve Sapp had voiced the opinion that this overlap was unacceptable due to concern with passivation integrity (although it looks like new Fujitsu layout will overlap the UBM over source AI). (wire-260.jpg)

Ex' +i+ 4 (page 3/7)

Thanks to Wayne Hurst and Ann tte Pieper for sample preparation, photos and input for this write-up. They are a little backed up for FA work at present. Thanks, Steve

Report 3/5 - Wireless SO-8

---- Forwarded by Steve Pritchett/SaltLake/Fairchild on 04/21/99 06:32 PM -----

1

Steve Pritchett 04/21/99 03:31 PM

To:

Rajeev Joshi/SantaClara/Fairchild@Fairchild, Ma Cristina B Estacio/Cebu/Fairchild@Fairchild, Consuelo N Tangpuz/Cebu/Fairchild@Fairchild, Honorio T Granada Jr/Cebu/Fairchild@Fairchild, Lester O

Uy/Cebu/Fairchild@Fairchild

cc:

Steven Sapp/SantaClara/Fairchild@Fairchild, Bruce Marchant/SaltLake/Fairchild@Fairchild, John R Diroll/SaltLake/Fairchild@Fairchild, R Evan Bendall/SaltLake/Fairchild@Fairchild, Henry W Hurst/SaltLake/Fairchild@Fairchild, Annette Pleper/SaltLake/Fairchild@Fairchild, Gordon

Madson/SaltLake/Fairchild@Fairchild

Subject: Report 3/5 - SO-8 Leadframe

I have broken this up into 4 emails/reports due to many photos.

- 1. Flipchip samples, some with gate to source shorts, some with black "corrosion" stain. (sent 4-19)
- 2. Wireless samples from Steve Sapp, SO-8 good/bad ?, identify cause of high Rdson. (sent 4-20)
- SO-8 wireless samples prior to molding, sent per SL request to help understand leadframe layout.

4. Bare die samples with bumps, sent per SL request.

5. Samples of SOT-223 wireless parts sent to SV, construction analysis. (still in que)

SO-8 wireless leadframe samples were sent from Cebu with objective of allowing SL to view assembly components.

SUMMARY - Good photo of Al metal not covered by UBM or passivation. D/A die position appears to be highly variable and source of bump to leadframe alignment variation.

As received, the parts had been through bump reflow, but not molded.

The following photos are observations. Cebu will need to access if these are problems, not representative of current process, etc.




This shows bump and passivation opening at edge of bump. Al metal is not protected! (s08lf3.jpg & so8lf1.jpg)



Interesting photo of crack beginning across bump. This part was manually cut from leadframe strip prior to SEM. Crack may have been caused by singulation? (so8lf2.jpg)



(so8lf12t.jpg & so8lf12e.jpg)



(so8lf14t.)pg & so8lf14e.jpg)



These three sets of photos show the variation in horizontal die position along with impact to bump alignment. Gate bump appears to be fully "squished" in photos. Stress relief for squished bumps is probably minimal. (so8lf16t.jpg & so8lf16e.jpg)

Thanks to Wayne Hurst and Annette Pieper for sample preparation, photos and input for this write-up. They are a little backed up for FA work at present.

Exhi¹ + 1 (page 5/2)

Thanks, Steve

Report 4/5 - Bare die

-- Forwarded by Steve Pritchett/SaltLake/Fairchild on 04/21/99 06:32 PM -----

Steve Pritchett 04/21/99 03:40 PM

To:

Rajeev Joshi/SantaClara/Fairchild@Fairchild, Ma Cristina B Estaclo/Cebu/Fairchild@Fairchild, Consuelo N Tangpuz/Cebu/Fairchild@Fairchild, Honorio T Granada Jr/Cebu/Fairchild@Fairchild, Lester O Uy/Cebu/Fairchild@Fairchild

CC:

Steven Sapp/SantaClara/Fairchild@Fairchild, Bruce Marchant/SaltLake/Fairchild@Fairchild, John R Diroll/SaltLake/Fairchild@Fairchild, R Evan Bendall/SaltLake/Fairchild@Fairchild, Henry W Hurst/SaltLake/Fairchild@Fairchild, Annette Pieper/SaltLake/Fairchild@Fairchild, Gordon Madson/SaltLake/Fairchild@Fairchild

Subject: Report 4/5 - Bare-die

I have broken this up into 4 emails/reports due to many photos.

- 1. Flipchip samples, some with gate to source shorts, some with black "corrosion" stain. (sent 4-19)
- 2. Wireless samples from Steve Sapp, SO-8 good/bad ?, identify cause of high Rdson. (sent 4-20)
- 3. SO-8 wireless samples prior to molding, sent per SL request to help understand leadframe layout (sent 4-20)
- 4. Bare die samples with bumps, sent per SL request.
- 5. Samples of SOT-223 wireless parts sent to SV, construction analysis. (still in que)

Wireless die samples, wafer Z009EM20KJ - 03 were sent from Cebu with objective of allowing SL to examine bumped die.


SUMMARY - No UBM overlap. Some backside metal peel exhibited. D/A or pick operation causing backside chips.

Note: JPG files for these photos are available upon request.

As received, the wafer had been bumped, backside metallization and diced. Also probe/sort/ink with most good die already removed from film.

The following photos are observations. Cebu will need to access if these are problems, not representative

of current process, etc.



These 2 photos show opening, exposing Al metal, between passivation and UBM. Some Al erosion is present. UBM contact area nealy the same as passivation opening (no wedge of contamination or etch undercut). (die4.jpg & die3.jpg)



The chip of Si remaining on dicing film shows a repeated pattern. Since we have seen cracked die on 80-100V FA samples, concern was for chipped out die may be more susceptable to cracking. (die2.jpg.)



A strip of backmetal peeled from portions of 3 die and remains on film. Concern is for FA samples where we have seen indications of missing or peeling backmetal. (die1.jpg)

The FA folks have suggested that assembly information/observations should be routine for builds going into reliability testing, especially if the die are being put in packages which require modified bonding or hand placement of die on lead frames. Example of this would be Dean's 100V parts which were put in non-satndard package and had unique bonding. These (100V) parts had cracks and BMP. The assembly observations should be included with parts.

Thanks to Wayne Hurst and Annette Pieper for sample preparation, photos and input for this write-up. They are a little backed up for FA work at present. Thanks, Steve

Cebu's comments:

Clemens Quinones 04/22/99 08:47 AM

To:

CC:

Steve Pritchett/SaltLake/Fairchild@Fairchild

Rajeev Joshi/SantaClara/Falrchild@Falrchild, Ma Cristina B Estacio/Cebu/Fairchild@Falrchild, Consuelo

N Tangpuz/Cebu/Fairchild@Fairchild, Honorio T Granada Jr/Cebu/Fairchild@Fairchild, Lester O

Uy/Cebu/Fairchild@Fairchild, Steven Sapp/SantaClara/Fairchild@Fairchild, Bruce

Marchant/SaltLake/Fairchild@Fairchild, John R Diroll/SaltLake/Fairchild@Fairchild, R Evan Bendall/SaltLake/Fairchild@Fairchild, Henry W Hurst/SaltLake/Fairchild@Fairchild, Annette

Pieper/SaltLake/Fairchild@Fairchild, Gordon Madson/SaltLake/Fairchild@Fairchild

Subject: Report 2/5 - Wireless SO-8

Hi Steve.

Aside from the gross wafer bumping problems, cross-section photos below represents majority of the good SO-8 wireless units assembled using the old leadframe design (with U-groove/ mold compound

EXMIDIT 4 (page 1/1)

channel). U-grooving on topframe has more disadvantages than its desired purposes such as solder joint wicking when bumps happen to touch the edge of topframe contact pad, missing solder joint when solder reflow totally int u-grooves (mostly affects gate causing maj rity f test yield loss) and non-reflow of solder when the bump hides within th u-groove. Downset poor coplanarity f topframe's gate & source contact pads is also on of the cause why som bumps aren't reflowed well.

I decided to modify the leadfram design. U-grooves from topframe are removed and punch through holes are placed instead. Total volume of removed metal in the new design is almost equal to the volume removed due to U-grooving of old leadframe design. Pls click on icon for assessment details -> Extra respectively. Further assessment is done to check for solder wetting coverage, solder wicking, mold delamination and others.

Currently, all samples are still using the old leadframe design. Once the current WIP will be flushed out, the next batches of samples will be using the new leadframe design. Expected timeframe will be May.

Clemens



Subject:

>1st T am Meeting

R sponse to:

TEAM MEETINGS

Categ ry:

Wireless SO-8 Pkg Dev't (Single Strand Approach)

SOIC-8 WIRELESS 1ST TEAM MEETING

<<<< MINUTES OF THE MEETING >>>>>

DATE : 23 FEB. 99 TIME : 1530h

VENUE: Synergy Room #1

ATTENDEES:

Reynaldo Gandionco

Oliver Ledon (Assembly

(Prodn)

COE)

Clemens Quinones

Rusty Vega Jr. (F/E

Reynaldo Sondo (EOL

(PTG)

Process Engig)

COE)

Marvin Gestole (PTG)

Emmanuel Livelo (F/E

Jun Soriba (EOL COE)

Process Eng'g)

Santos Mepieza (PTG

Noel Laylo (EOL & T/F

Lester Uy (Rel & F/A)

Support)

Process Eng'g)

Rey Maligro (PTG

Dexter Sorono (EOL.

Rocil Tindugan (QA

Support)

Process Eng'g)
Allan Ermac (Fab

Eng'g)
Engelbert Romero (QA

Darwin Linao (PTG Support)

Process Eng'g) Eng'g)

AGENDA:

- 1. WIRELESS PACKAGING HISTORY
- 2. SOIC-8 WIRELESS PKG. CONSTRUCTION
- 3. SOIC-8 WIRELESS FRONT END ASSY PROCESS FLOW
- 4. SOIC-8 WIRELESS EOL PROCESS FLOW
- 5. OPEN ISSUES

DISCUSSIONS:

=> wireless packaging brief history

- + wireless technology development started 1996 in SOT-223 pkg
- + SO-8 wireless package development started June 1998.
- + basic learnings in SOT-223 wireless package applied to SO-8 wireless pkg
- + first SO-8 wireless prototyping attempt on matrix frame very complicated and discontinued
- + simultaneous development on single strand proven feasible and easy
- + final approach to SO-8 wireless packaging is full sandwich assembly with overlapping top & bottom I/f

=> SOIC-8 wireless package construction

DAP + D/A mat'l + Si trench die + solder bumps + gate & source terminal contacts + molded body

=> SOIC-8 wireless assembly process flow (Latest updates included)

Front End Assembly Flow (Option #8)

1. SOFT SOLDER DIE ATTACH (ESEC 2005HR di attach)

Obstacle 1: Die to topframe alignment not so good due to marginal DAP allowance for die placement. Missing gate balls (after reflow).

>> Modification of topframe required to allow bigger die placement tolerance and better die attach position/ placement. Remove U-grooves of topframe.

Resp. Clemens

Status: Changes incorporated in Rev. N topframe design. FAI samples to arrive by March 31 yet.

2.0 FLUX DISPENSING (ESEC cutter converted to flux dispenser)

Obstacle 2: Flux distribution on die not good

>> flux dispensing tool need to conform die design. Fabricate flux dispensing tool designed for wireless dice (5A & 5F).

Resp. Clemens/ Bibi/ Eman

Status: Awaiting final quotation from Micro-mechanics (vendor)

3. TOP FRAME ATTACH

Obstacle 3: Top Frame & bottom frame misalignment resulting to EOL problems.

>> Add bottom & top frame alignment press-fit studs & holes

Resp: Clemens

Status: Changes incorporated in Rev. P bottomframe & Rev. N topframe design. FAI samples to arrive by March 31 yet

Obstacle 4: Topframe attach process currently on manual mode (along with rail spot welding process)

>> this process will be incorporated with the flux dispensing to avoid manual handling. ESEC cutter for flux dispensing will be annexed with auto top frame attach + rail stamping for press fitting stud & hole.

Resp: Santos & Oliver

Status: On going machanical parts drafting & PLC program development

 RAIL SPOT WELDING (using tabletop leadframe alingment jig & C-clamp welding tips)

Obstacle 5: Manualithic process using a table top welding jig. >> Longterm action item: Employ automated laser welding for non-contact welding

Resp: Marvin & Clemens

Status: Technical discusion with vendor is ongoing. Purchase spec to be drafted. PPA to be generated yet.

5. SOLDER REFLOW

Option 1: Using dixsealer (for small volume)

Obstacle 6: No dedicated offline dixseal programmer

>> clone off-line programmer to be assembled before shipping out sold dixsealers to China. FSCB to use the clone programmer.

Resp: Bernard Benjamin & Edgar Baguio

Status: On going

Exhibit 5 Cyuga -/17/

Opti n 2: Using conv yorized IR reflow ven (for mass

production)

Obstacle 7: IR oven process parameters not yet optimized.

>> process optimization to b don wh n mor bumped wafers are available. More waf rs available by WW42.

Resp: Cl mens & R y M.

End of Line Assembly Flow (Option #1)

 MOLDING (2-chase mold mounted on Sumitomo press from SOT)
 Obstacle 8: In-house buy-off stage - molded strips encountered blown dambar & leads.

>>in-depth troubleshooting of molding process required.

Resp. Marvin/Dexter S/ Jun S

Status: SungWoo engineers to assist troubleshooting on day1-WW41.

7. POST MOLD BAKE (1-hour)

Obstacle 9: Prod'n favors no PMB. PMB is required to strengthen pkg surface to resist rough pkg during deflashing.

>>Eval required to determine the need for deflash jig.

Resp: Clemens & Darwin Status: Eval on going

8. DDD - Degate/Dejunk/Debar (share same press with TNF)

Obstacle 10: Tool & Press still in Korea. Shipment is pending completion of TNF tool buy-off.

>> Expedite TNF tool buy-off.

Resp: Marvin

Status: Final leadformed units ongoing dimensional buy-off in Cebu. Press, DDD & TNF tool to be shipped to FSCB on WW41

9. **DEFLASH** (Hitch with std SOT-23 plastic media deflasher. By May, one full-time plastic media deflasher will be released when other pkgs migrate to H2O jet deflash.)

Obstacle 11: Are jigs required for deflashing? (See Obstacle 9) Which deflasher to convert?

>> Cyrus to identify what deflasher to convert. Deflash track & transport system to be fabricated.

Resp: Marvin & EOL COE

Status: Designing/ plans to start upon advise of Cyrus on what deflasher to use.

10. LASER MARK

Option 1: Ride-on with YAG using strip carrier/ jig for small volume

Obstacle 12: Jig design not suitable for jamming-free transport. Laser mark programming not yet done.

>> Jig modification required for steady vertical Y-axis leadframe support.

Resp: Clemens & Dexter S.

Status: Modified jig fabrication ongoing. Dexter to program laser marking with the modified jig.

Opti n 2: Offline Strip Marker for mass production

Exhibit 5 (page 4/4)

>> Retrieve strip marker from Covertek for tranport mechanism modification

Resp: Rey S/ Jun S

Status: Retrieval of archived stripmarker - WW41

11. POSTPLATE (us SOT-23 plating racks & ride-on SO-8 platingline)

12. TRIM & FORM (share same press with TNF) See DDD

=> other open issues:

- 1. Lay-out (Resp: Lyle)
- 2. Headcount allocation/forecast (Resp. Clemens)
- 3. Qual Plan/ Definition of requirements (Resp. Clemens)
- 4. Updated Cost/CLD (Resp. Clemens)
- 5. Documentations:
 - DFMEA (Resp: Clemens)
 - Prototype Control Plan (Resp: Clemens)
 - Pre-launch Control Plan (Resp: Clemens)
 - Qualification Plan (Resp: Clemens)
 - PCN required? (Resp. Clemens or SV)
 - Rejection Criteria (Resp. Arlene R.)
 - Process Specifications (Resp: Process Eng'rs)
 - Soft Solder D/A to Reflow = Eman
 - Molding to TNF = Dexter S.





Fairchild Semiconductor 333 Western Avenue South Portland, Maine 04106

June 4, 1999

Babak Sani, Esq. Townsend, Townsend & Crew Two Embarcadero Center, 8th Floor San Francisco, CA 94111

Re:

Invention Disclosure entitled High Performance SOIC-8 DMOS

Inventors: Maria Clemens Y. Quinones, et al.

Our Reference No. 17732-9833

Dear Babak:

Enclosed is the above entitled invention disclosure for drafting into a patent application. There are several inventors involved in this application and they are all located in the Philippines. Rajeev Joshi will be the contact person here, so please contact Rajeev directly in Sunnyvale at 408.822.2163.

Please confirm receipt of this file and let me know the client matter number assigned. As with other files assigned to your firm, please include the FSC reference number on all documents/correspondence with copies to Pierce Atwood.

Thanks for your assistance.

Best regards,

Kate Oliver

Administrative Associate, Legal

cc:

Rajeev Joshi

Chris Caseiro, Esq.







Palo Alto, California Tel 650 326-2400

Seattle, Washington Tel 206 467-9600 San Francisco

Two Embarcadero Center Eighth Floor San Francisco California 94111-3834 Tel 415 576-3200 Fax 415 576-3300

> Direct Dial (415-2) in Links BSS@Tourisand in a

June 7, 1999

Daniel E. Boxer. Esq.
Executive Vice President, General Counsel
and Chief Executive Officer
FAIRCHILD SEMICONDUCTOR CORPORATION
333 Western Ave., Mail Stop 01-00
South Portland, ME 04106

Re:

VERTICAL MOSFET WITH ULTRA LOW-ON

RESISTANCE AND GATE CHARGE PERFORMANCE

Your Ref: 17732-9827 / Our File: 018865-003300US POWER MOS DEVICE WITH IMPROVED GATE CHARGE PERFORMANCE

V - D - C 17722 0020 / O. Tile 0100

Your Ref: 17732-9830 / Our File: 018865-003400US -- and --

HIGH PERFORMANCE SOIC-8 DMOS

Your Ref.: 17732-9833 / Our File: 018865-003500US

Dear Dan:

Receipt is confirmed of the referenced invention disclosures, for which we will begin with the preparation of patent applications. We will keep you apprised of the status of these matters. If you have any questions, please feel free to call.

Regards,

Babak S. Sani

BSS:deb

cc: Chris A. Caseiro, Esq.

SF 1001487 v1



9/20/99 - eliminate wire boud completely - placing another lead trane on tops - grows are vedaced by 5/ots - Together relding to keep Frames
together
- 19 19 5agr Now Kitting but
actually now soot welding

TOWNSEND
and
TOWNSEND
and
CREW

Denver, Colora Tel 303 571-4000 Palo Alto, California

Tel 650 326-2400

Seattle, Washington Tel 206 467-9600 San Francisco

Two Embarcadero Center Eighth Hoor San Francisco California 94111-3834 Tel 415 576-0200 Fax 415 576-0300

₹.

November 19, 1999

VIA FEDERAL EXPRESS

Maria Clemens Y. Quinones FAIRCHILD SEMICONDUCTOR, PEZA Dept. PTG, #02-3450 Lapulapu City, Cebu 6015 PHILIPPINES

Re:

Draft Patent Application

For: IMPROVED METHOD OF MAKING A

CHIP DEVICE

Client Ref: 17732-9833

Our File No.: 018865-003500US

Dear Ms. Quinones:

Here is a draft of a patent application for the Improved Method Of Making A Chip Device, specifically, the patent application for the packaging of the high-performance SOIC-8 DMOS. You and the other inventors should review it carefully for content and accuracy. After you have done so, please provide me with any comments and changes that you may have. I will then incorporate them into the patent application so that we may file it with the U.S. Patent and Trademark Office.

Please note that in the disclosure, specifically, the drawing labeled "Part 4: Solder Bumps," reference is made to "UBM:TiW/Cu/Au or equivalent." I did not include this in the application since I am not clear as to what "UBM" refers. Thus, please provide me with this information so that I may include it in the patent application.

I look forward to hearing from you soon. Should you have any questions, please do not hesitate to contact me.

Best regards,

'Kevin T. LeMono

KTL:rgh

Enclosure

cc:

Daniel E. Boxer, Esq. (via U.S. Mail w/o encl.) Chris A. Caseiro, Esq. (via U.S. Mail w/o encl.)

SF 1045590 v1

From:

"Clemens Quinones" < Clemens. Quinones@notes.fairchildsemi.com>

T:

"Kevin L Mond" <KTL@townsend.com>

Date: Subject: Sun, Dec 5, 1999 5:09 PM Fairchild Ref. No. 17732-9833

Hi Kevin.

Greetings!

This is to inform you that I received the draft for patent application on IMPROVED METHOD OF MAKING A CHIP DEVICE. Thanks a lot for the enormous efforts done on drafting this document.

The item you left in majority of die & bump descriptions, i.e., the UBM, is an essential part of the solder bump structure. UBM stands for Under Bump Material. It is an intermediate layer between die & solder bump. Metallurgy for UBM cited for this patent is TiW/Cu/Au or equivalent. Attached drawing is example of UBM currently used for this package:

(See attached file: Die,UBM&bump_structure.doc)

Die, UBM & solder bump always come as one in this patent application. For ease in description/nomenclature, we can call it collectively as. "bumped die".

During review of the draft, herebelow is the list of lines that are affected with above changes and other relevant corrections too.
(P refers to Page, L refers to Line)

- P1,L31: change from "plurality of memory devices" to "plurarity of DMOS devices"
- P1,L32-P2,L1-4: (Pls change the description to match the bumped die description.)
- P2,L17-19: (Pls change description to match the bumped die description. My suggestion"In accordance with a further aspect of present invention, bumped dies are placed on topframe such that solder bumps are in direct contact with topframe.")
- P3,L23: change from "perspective view of a top leadframe" to "perspective view of an inverted top leadframe"